

TO FIT SIZE CHART

*Measurements refer to body size, not garment dimensions



R316X - LITE JACKET

25.02.2016

	XS	S	M	L	XL	2XL	3XKL	4XL
Full chest in inches*	36	38	41	44	47	50	54	56
Full chest in cm*	91,44	96,52	104,14	111,76	119,38	127	137,16	142,24
German clothing size (men)	46	48	50	54	56	60	64	68

HOW TO MEASURE CHEST: Place the tape measure across the back, underneath the arms and then across the fullest part of the chest.

1 Inch = 2,54 cm